


St. Mary's County MetCom

6204
WO/31708



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	SS ICR
Inspection Number			
Property Address	44561 Bellview Ct.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Vault needs a riser, lid was buried in the front yard garden.
Alarm Light work, Alarm does not

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6265
WO/31709



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	JR CR
Inspection Number			
Property Address	4457A	Belview Ct.	
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	<u>No</u>	Present, but not tested
-----	-----------	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

<u>Yes, note issues below in observations</u>	No
---	----

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:


<i>Bushes blocking access to the panel</i>
<i>Alarm Light works but no sound</i>

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

10266

WD 31710



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	JJ CR
Inspection Number			
Property Address	44580	Bellview Ct	
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Bush blocking access to panel
Roots in vault, cleared the vault up, took roots out

Alarm light is on, NO SOUND

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

0267

St. Mary's County MetCom



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	JJ CC
Inspection Number			
Property Address	44581 Bellview Ct.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Large Bush blocking access to panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6268
WD 31712



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	JJ CR
Inspection Number			
Property Address	44590	Bellview Ct.	
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
-----------------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Bush blocking access to the panel.
Vault Cover is cracked in multiple spots.
Alarm Light works no Alarm Sound

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

10269
WO 31713



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	JJ CR
Inspection Number			
Property Address	44600 Bellview Ct.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
-----------------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Vault cover is cracked, Bushes covering up the control panel
Alarm Float Light works but Alarm does not sound.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

0277

WO 31717



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	JJ CR
Inspection Number			
Property Address	44601 Bellview Ct.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Float & Light DO NOT WORK

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6270
WO 31714



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	W CR
Inspection Number			
Property Address	44610 Belview Ct.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	<u>Poor</u>	Immediate Action
-----------	------	------	-------------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Light & Alarm for float DO NOT WORK
Also the connections inside the vault could be re-done

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6271



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	JR CR
Inspection Number			
Property Address	44624 Bellview Ct		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:


There is 1 Bush blocking access to the panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6272

WO 31715



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	HW CR
Inspection Number			
Property Address	44631 Bellview Ct		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Multiple Bushes covering up ALL Access to the panel
The Alarm Float Light & Alarm DO NOT WORK

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6273

St. Mary's County MetCom

Grinder Pump Field Inspection Form



Date of Inspection	1/18/24	Inspector Initials	JL CL
Inspection Number			
Property Address	44634 Bellview Ct.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input checked="" type="radio"/> Yes, note issues below in observations	<input type="radio"/> No
---	--------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

(2) 7ft Bushes covering up the whole panel blocking all access to the panel.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6274
WO 31716



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	JR CR
Inspection Number			
Property Address	44637 Bellview Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm works on Float but light for Alarm on panel does not

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	JY CR
Inspection Number			
Property Address	44639 Bellview Ct.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6278



Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	Inspector Initials	W CR
Inspection Number			
Property Address	44645 Bellview Ct		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).