


St. Mary's County MetCom

Grinder Pump Field Inspection Form

ID 6180

WO 31617



Date of Inspection	January 8 2024 (0750)	Inspector Initials	BMG B. Green
Inspection Number			
Property Address	15914 Camp Merryclande RD P.ney Point MD 20674		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input checked="" type="radio"/> Vented	<input type="radio"/> Non-Vented
---	----------------------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

I&I on Entry pipe into well. (pictured)
Pump chains need to be replaced with stainless steel chain to prevent rust.

Repairs needed (if any) and estimated schedule for completion:

- see above noted -

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6369



Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	Inspector Initials	mm	
Inspection Number				
Property Address	16036 CAMP MERRILLANDS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input type="radio"/> Good	<input type="radio"/> Missing	<input checked="" type="radio"/> Broken	<input type="radio"/> offset
----------------------------	-------------------------------	---	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6370



Grinder Pump Field Inspection Form

Date of Inspection	11/27/24	Inspector Initials	MAM	
Inspection Number				
Property Address	16045 CAMP MARY ELANDE RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	Unknown, add comments in observations
--------------------------------------	--------------------------	---------------------------------------

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Vault is surrounded by grass in front yard

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6371



Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	Inspector Initials	mm
Inspection Number			
Property Address	16060 Camp Merrylands Rd		
Weather Conditions	Rain	Snow	Sunny
			Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NO POWER GOING TO THE GRINDER PUMP THE DRAINING IS
UNOCCUPIED

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6372



Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	Inspector Initials	mm	
Inspection Number				
Property Address	16061 CAMP MOREYELANDIE RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6373



Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	Inspector Initials	mm
Inspection Number			
Property Address	16065 Camp Merry Islands Rd		
Weather Conditions	Rain	Snow	Sunny
			Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).