


6987

Grinder Pump Field Inspection Form

WO 32027



Date of Inspection	2/18/24	Inspector Initials	E. Pool T.S.
Inspection Number			
Property Address	45054	St. Georges Park Rd	Troopers Rd.
Weather Conditions	Rain	Snow	Sunny
			Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	---------------

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Bed Alarm float light works but no audible fence with aggressive dogs

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6789



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	J. D. H. F.	
Inspection Number				
Property Address	45029 Trooper Rd.			
Weather Conditions	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6790



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	<i>[Signature]</i>
Inspection Number			
Property Address	45030 Trooper Rd.		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> <u>Cloudy</u>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).