

St. Mary's County MetCom

10722



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/29/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17837 4th St.		
<b>Weather Conditions</b>	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6724  
WO 31913



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/29/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17838 4 <sup>th</sup> St.		
<b>Weather Conditions</b>	Rain	Snow	Sunny <u>cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Roots growing in around inlet pipe
Both visual and audible alarms not working

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6709  
WO 31906



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/29/2024	<b>Inspector Initials</b>	LN CB	
<b>Inspection Number</b>				
<b>Property Address</b>	17841	4 <sup>th</sup>	Street	
<b>Weather Conditions</b>	Rain	Snow	Sunny	<u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

I & I trickling in around inlet pipe

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6713



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/29/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17842 4 <sup>th</sup> Street		
<b>Weather Conditions</b>	Rain	Snow	<del>Sunny</del> <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6932



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	JJ OF
Inspection Number			
Property Address	17845 4th Street		
Weather Conditions	Rain	Snow	Sunny <input checked="" type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	No	Unknown, add comments in observations
--------------------------------------	----	---------------------------------------

What type of pump is this?

<input checked="" type="radio"/> Meyers	Barnes	Retrofit	E1
---	--------	----------	----

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	Good	Fair	Poor	Immediate Action
--	------	------	------	------------------

What is the condition of the cover?

<input checked="" type="radio"/> Good	Missing	Broken	offset
---------------------------------------	---------	--------	--------

What type of cover is installed?

Vented	<input checked="" type="radio"/> Non-Vented
--------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	Good	Fair	Poor	Immediate Action
--	------	------	------	------------------

Is an isolation valve present?

<input checked="" type="radio"/> Yes	No
--------------------------------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="checkbox"/> Yes, note issues below in observations	<input checked="" type="checkbox"/> No
---	--

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6931



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	<i>[Handwritten initials]</i>
Inspection Number			
Property Address	17846 4th Street		
Weather Conditions	Rain	Snow	Sunny <input type="checkbox"/> Cloudy <input checked="" type="checkbox"/>

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is the audible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Is the visible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Are there any accessibility issues (shrubs, trees, fences)?**

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6933



Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	Inspector Initials	<i>[Signature]</i>
Inspection Number			
Property Address	17849	4 <sup>th</sup> Street	
Weather Conditions	Rain	Snow	Sunny <input checked="" type="radio"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

**What is the condition of the electrical panel?**

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

**Is the audible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Is the visible alarm present and functioning?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

**Are there any accessibility issues (shrubs, trees, fences)?**

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6984

# St. Mary's County MetCom



## Grinder Pump Field Inspection Form

Date of Inspection	2/6/24	Inspector Initials	LN
Inspection Number			
Property Address	17850 4th st		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6985

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**



<b>Date of Inspection</b>	2/6/24	<b>Inspector Initials</b>	LN
<b>Inspection Number</b>			
<b>Property Address</b>	17853 4th st		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

**What is the condition of the vault?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6986

**St. Mary's County MetCom**



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	2/6/24	<b>Inspector Initials</b>	LN
<b>Inspection Number</b>			
<b>Property Address</b>	17854 4th st		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

**What is the condition of the vault?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

**What is the condition of the electrical panel?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is the audible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Is the visible alarm present and functioning?**

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	<u>No</u>
--	-----------

**Are there any obvious signs of I&I (ie. clearwater flow)?**

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

0727  
WO 31914



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/29/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17856 4th St.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

**What is the condition of the vault?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is an isolation valve present?**

<u>Yes</u>	No
------------	----

✓

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Junction box is hanging down by cables in vault

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6909



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/29/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>	17857 4th St		
<b>Property Address</b>	Deagles Boat Yard Rd (By 3rd St. no address)		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

17857 4th St

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault? ✓

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

What is the condition of the cover? ✓

Good	Missing	<u>Broken</u>	offset
------	---------	---------------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.) ✓

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is an isolation valve present? ✓

Yes	No
-----	----

What is the condition of the electrical panel? ✓

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning? ✓

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning? ✓

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)? ✓

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

vault does not have an address. Abandoned
Cover is cracked and broken. Full of water
side of road near 3 <sup>rd</sup> St.

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6729  
WD 31915



Grinder Pump Field Inspection Form

<b>Date of Inspection</b>	1/29/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17858 4th Street		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	Good	<u>Fair</u>	Poor	Immediate Action
-----------	------	-------------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	<u>Minor signs of I&amp;I (weeping or trickle)</u>	Major (gushing)
-----------------	--	-----------------

Other Observations, any "Immediate Action" taken should be described:

I&I coming in around junction box pipe

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**  
**Grinder Pump Field Inspection Form**

6735  
WD 31916



<b>Date of Inspection</b>	1/29/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17859 4 <sup>th</sup> St.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

<u>vault nearly underwater after rain</u>

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6740  
WO 31918



<b>Date of Inspection</b>	1/29/2024	<b>Inspector Initials</b>	LN CB
<b>Inspection Number</b>			
<b>Property Address</b>	17861 4 <sup>th</sup> St.		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="checkbox"/> Unknown, add comments in observations
--------------------------------------	--------------------------	--

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&amp;I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

vault is nearly underwater after rain

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).