

St. Mary's County MetCom

6693



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	WJH
Inspection Number			
Property Address	44890 Shore Dr		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------


Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6094



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	MZ
Inspection Number			
Property Address	44895	Shore Dr.	
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6695



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	JF RW
Inspection Number			
Property Address	44900 Shore Dr.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6696



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	JH
Inspection Number			
Property Address	44901 Shore Dr		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6697



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	W JH
Inspection Number			
Property Address	44902 Shore Dr.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6698

Grinder Pump Field Inspection Form

WD 31903



Date of Inspection	1/23/24	Inspector Initials	JRH
Inspection Number			
Property Address	44936 Shore Dr.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input type="radio"/> Yes	<input checked="" type="radio"/> No	<input type="radio"/> Present, but not tested
---------------------------	-------------------------------------	---

Is the visible alarm present and functioning?

<input type="radio"/> Yes	<input checked="" type="radio"/> No	<input type="radio"/> Present, but not tested
---------------------------	-------------------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6699



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	MJW
Inspection Number			
Property Address	44939	Shore Dr.	
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6709



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	RZH
Inspection Number			
Property Address	44940 Shore Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

What type of pump is this?

<input checked="" type="radio"/> Meyers	<input type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
---	------------------------------	--------------------------------	--------------------------

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

What is the condition of the cover?

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

What type of cover is installed?

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is an isolation valve present?

<input checked="" type="radio"/> Yes	<input type="radio"/> No
--------------------------------------	--------------------------

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------


Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6701



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	MFB
Inspection Number			
Property Address	44945	Shore Dr.	
Weather Conditions	Rain	Snow	Sunny <input checked="" type="checkbox"/> Cloudy

Does MetCom own the grinder pump?

<input checked="" type="radio"/> Yes	No	Unknown, add comments in observations
--------------------------------------	----	---------------------------------------

What type of pump is this?

<input checked="" type="radio"/> Meyers	Barnes	Retrofit	E1
---	--------	----------	----

What is the condition of the vault?

<input checked="" type="radio"/> Excellent	Good	Fair	Poor	Immediate Action
--	------	------	------	------------------

What is the condition of the cover?

<input checked="" type="radio"/> Good	Missing	Broken	offset
---------------------------------------	---------	--------	--------

What type of cover is installed?

Vented	<input checked="" type="radio"/> Non-Vented
--------	---

Condition of interior fixtures (guide rails, electrical connections, etc.)

<input checked="" type="radio"/> Excellent	Good	Fair	Poor	Immediate Action
--	------	------	------	------------------

Is an isolation valve present?

<input checked="" type="radio"/> Yes	No
--------------------------------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6912

St. Mary's County MetCom

Grinder Pump Field Inspection Form



Date of Inspection	1/23/24	Inspector Initials	JJH
Inspection Number			
Property Address	UNKNOWN ADDRESS (w/ St. George Park)		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Part
Pd pack)

44980 Shore Drive.

Does MetCom own the grinder pump?

Yes	<u>No</u>	<u>Unknown</u> , add comments in observations
-----	-----------	---

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Excellent	Good	Fair	<u>Poor</u>	Immediate Action
-----------	------	------	-------------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	<u>Poor</u>	Immediate Action
-----------	------	------	-------------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

1 Grinder Pump Vault with a Meyers pump, Rails, and an isolation valve inside of the vault. There is no panel for this grinder pump.
--

Repairs needed (if any) and estimated schedule for completion:

No Address, Grinder Pump Vault is located

ACROSS from (44971 Shore Drive) on the right side of the
--

ABANDONED Address found see front road.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6702



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	JH KH
Inspection Number			
Property Address	44988 Shore Dr.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	Inspector Initials	JR ZHB
Inspection Number			
Property Address	44996 Shore Dr.		
Weather Conditions	Rain	Snow	<u>Sunny</u> Cloudy

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

<u>Meyers</u>	Barnes	Retrofit	E1
---------------	--------	----------	----

What is the condition of the vault?

Vault?

Excellent	Good	Fair	<u>Poor</u>	Immediate Action
-----------	------	------	-------------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<input checked="" type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
--	----------------------------	----------------------------	----------------------------	--

Is the audible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Is the visible alarm present and functioning?

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Present, but not tested
--------------------------------------	--------------------------	---

Are there any accessibility issues (shrubs, trees, fences)?

<input type="radio"/> Yes, note issues below in observations	<input checked="" type="radio"/> No
--	-------------------------------------

Are there any obvious signs of I&I (ie. clearwater flow)?

<input checked="" type="radio"/> No signs of I&I	<input type="radio"/> Minor signs of I&I (weeping or trickle)	<input type="radio"/> Major (gushing)
--	---	---------------------------------------

Other Observations, any "Immediate Action" taken should be described:

<i>Roots inside vault.</i>

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).