

**St. Mary's County MetCom**

6893

WO 31965



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/12/24	<b>Inspector Initials</b>	mm	
<b>Inspection Number</b>				
<b>Property Address</b>	46030 SHEAFFER LANE			
<b>Weather Conditions</b>	Rain	Snow	Sunny	Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

**What type of pump is this?**

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

**What is the condition of the vault?**

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

**What is the condition of the cover?**

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

**Is an isolation valve present?**

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**



**Repairs needed (if any) and estimated schedule for completion:**

NEEDS TO BE CLEANED OUT

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6894  
WO 31966 

<b>Date of Inspection</b>	11/2/24	<b>Inspector Initials</b>	mm
<b>Inspection Number</b>			
<b>Property Address</b>	46036 SHERIFF LANE		
<b>Weather Conditions</b>	Rain	Snow	<input checked="" type="radio"/> Sunny <input type="radio"/> Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	Unknown, add comments in observations
--------------------------------------	--------------------------	---------------------------------------

**What type of pump is this?**

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

**What is the condition of the vault?**

<input type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input checked="" type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	----------------------------	----------------------------	---------------------------------------	--

**What is the condition of the cover?**

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

**Is an isolation valve present?**

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**

TOP OF VAULT NEEDS REPAIRS WHERE IT BOLTS ON

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6895  
WO 31967



<b>Date of Inspection</b>	1/12/24	<b>Inspector Initials</b>	man
<b>Inspection Number</b>			
<b>Property Address</b>	46048 SHADOFFER LANE		
<b>Weather Conditions</b>	Rain	Snow	Sunny Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

**What type of pump is this?**

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

**What is the condition of the vault?**

<input type="radio"/> Excellent	<input type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input checked="" type="radio"/> Immediate Action
---------------------------------	----------------------------	----------------------------	----------------------------	---

**What is the condition of the cover?**

<input type="radio"/> Good	<input checked="" type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
----------------------------	--	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input type="radio"/> Non-Vented
------------------------------	----------------------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input type="radio"/> Excellent	<input type="radio"/> Good	<input checked="" type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	----------------------------	---------------------------------------	----------------------------	--

**Is an isolation valve present?**

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

VAULT NEED REPAIRING

Repairs needed (if any) and estimated schedule for completion:


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	11/2/24	<b>Inspector Initials</b>	mem
<b>Inspection Number</b>			
<b>Property Address</b>	46053 SHEPHERD LANE		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is an isolation valve present?**

Yes	<u>No</u>
-----	-----------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------


**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

6897



**Grinder Pump Field Inspection Form**

<b>Date of Inspection</b>	1/12/24	<b>Inspector Initials</b>	mm	
<b>Inspection Number</b>				
<b>Property Address</b>	46055 SHEAFFER LANE			
<b>Weather Conditions</b>	Rain	Snow	Sunny	Cloudy

**Does MetCom own the grinder pump?**

<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> Unknown, add comments in observations
--------------------------------------	--------------------------	---

**What type of pump is this?**

<input type="radio"/> Meyers	<input checked="" type="radio"/> Barnes	<input type="radio"/> Retrofit	<input type="radio"/> E1
------------------------------	---	--------------------------------	--------------------------

**What is the condition of the vault?**

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

**What is the condition of the cover?**

<input checked="" type="radio"/> Good	<input type="radio"/> Missing	<input type="radio"/> Broken	<input type="radio"/> offset
---------------------------------------	-------------------------------	------------------------------	------------------------------

**What type of cover is installed?**

<input type="radio"/> Vented	<input checked="" type="radio"/> Non-Vented
------------------------------	---

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair	<input type="radio"/> Poor	<input type="radio"/> Immediate Action
---------------------------------	---------------------------------------	----------------------------	----------------------------	--

**Is an isolation valve present?**

<input type="radio"/> Yes	<input checked="" type="radio"/> No
---------------------------	-------------------------------------

**What is the condition of the electrical panel?**

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

**Is the audible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Is the visible alarm present and functioning?**

Yes	No	Present, but not tested
-----	----	-------------------------

**Are there any accessibility issues (shrubs, trees, fences)?**

Yes, note issues below in observations	No
--	----

**Are there any obvious signs of I&I (ie. clearwater flow)?**

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

**Other Observations, any "Immediate Action" taken should be described:**


**Repairs needed (if any) and estimated schedule for completion:**


Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

**St. Mary's County MetCom**

**Grinder Pump Field Inspection Form**

6898

WO 31968



<b>Date of Inspection</b>	1/12/24	<b>Inspector Initials</b>	man
<b>Inspection Number</b>			
<b>Property Address</b>	46059 SHEPHERD LANE		
<b>Weather Conditions</b>	Rain	Snow	<u>Sunny</u> Cloudy

**Does MetCom own the grinder pump?**

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

**What type of pump is this?**

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

**What is the condition of the vault?**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**What is the condition of the cover?**

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

**What type of cover is installed?**

Vented	<u>Non-Vented</u>
--------	-------------------

**Condition of interior fixtures (guide rails, electrical connections, etc.)**

Excellent	<u>Good</u>	Fair	Poor	Immediate Action
-----------	-------------	------	------	------------------

**Is an isolation valve present?**

Yes	<u>No</u>
-----	-----------

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action
-----------	------	------	------	------------------

Is the audible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Is the visible alarm present and functioning?

Yes	No	Present, but not tested
-----	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No
--	----

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)
-----------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:


Repairs needed (if any) and estimated schedule for completion:

NEEDS CAP PUT ON CLEAN OUT

Photos should be sent to [opadmin@metcom.org](mailto:opadmin@metcom.org) with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).