


St. Mary's County MetCom

10846



Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	Inspector Initials	LN
Inspection Number			
Property Address	17679 Stewart petro pump Rd		
Weather Conditions	Rain	Snow	Sunny <u>Cloudy</u>

Does MetCom own the grinder pump?

<u>Yes</u>	No	Unknown, add comments in observations
------------	----	---------------------------------------

What type of pump is this?

Meyers	<u>Barnes</u>	Retrofit	E1
--------	---------------	----------	----

What is the condition of the vault?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

What is the condition of the cover?

<u>Good</u>	Missing	Broken	offset
-------------	---------	--------	--------

What type of cover is installed?

Vented	<u>Non-Vented</u>
--------	-------------------

Condition of interior fixtures (guide rails, electrical connections, etc.)

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is an isolation valve present?

<u>Yes</u>	No
------------	----

What is the condition of the electrical panel?

<u>Excellent</u>	Good	Fair	Poor	Immediate Action
------------------	------	------	------	------------------

Is the audible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Is the visible alarm present and functioning?

<u>Yes</u>	No	Present, but not tested
------------	----	-------------------------

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	<u>No</u>
--	-----------

Are there any obvious signs of I&I (ie. clearwater flow)?

<u>No signs of I&I</u>	Minor signs of I&I (weeping or trickle)	Major (gushing)
----------------------------	---	-----------------

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).